

## ■ SURFACE MOUNTING SOCKET OUTLETS ANGLED BOX

XENIA Series



Poles	Volt	Hz.	h.	16A	
2P+E	100-130	50/60	4	514.1650	10/40
2P+E	200-250	50/60	6	514.1653	10/40
3P+E	380-415	50/60	6	514.1656	10/40
3P+N+E	346-415	50/60	6	514.1657	10/40

  

Poles	Volt	Hz.	h.	32A	
2P+E	100-130	50/60	4	514.3250	10/40
2P+E	200-250	50/60	6	514.3253	10/40
3P+E	380-415	50/60	6	514.3256	10/40
3P+N+E	346-415	50/60	6	514.3257	10/40

## ■ SURFACE MOUNTING SOCKET OUTLETS STRAIGHT BOX

OPTIMA Series



Poles	Volt	Hz.	h.	16A	
2P+E	100-130	50/60	4	522.1650	10/50
2P+E	200-250	50/60	6	522.1653	10/50
3P+E	380-415	50/60	6	522.1656	10/50
3P+N+E	346-415	50/60	6	522.1657	10/50

  

Poles	Volt	Hz.	h.	32A	
2P+E	100-130	50/60	4	522.3250	10/40
2P+E	200-250	50/60	6	522.3253	10/40
3P+E	380-415	50/60	6	522.3256	10/40
3P+N+E	346-415	50/60	6	522.3257	10/40

### TERMINALS



SCREW  
TERMINALS



SPRING  
TERMINALS



FAST WIRING - Anti vibrations



INSULATION  
PERFORATING  
TERMINALS



FAST WIRING



MANTLE  
TERMINALS



Optimal connections for high currents.